

Issued: July 4, 2022

Program: Roofer (Roofer, Damp, and Waterproofer)

To: ITA Training Providers
Articulation Chair
System Liaison Person
Youth Train in Trades School Districts

Subject: **Roofer (Roofer, Damp, and Waterproofer) Program Update**

OPSN No.: **OPSN 2022 012**

Effective Date: September 1, 2022

Summary of Change: Please be advised that the Harmonized Program Outline and Program Profile have been posted to the Industry Training Authority (ITA) [website](#). Changes were made to the trade name, technical training (TT) hours, work-based training (WBT) hours, and program content.

Details: Changes to the Roofer (Roofer, Damp, and Waterproofer) program in BC are as follows:

Trade Name: Changed from **Roofer, Damp, and Waterproofer** to **Roofer**

Hours: See table below

	Current Hours	Harmonized Hours	Difference
Level 1	120	150	+30
Level 2	120	150	+30
Level 3	120	150	+30
Total Technical Training	360	450	+90
Work-based Training	3,600	4,950	+1,350
Total Training	3,960	5,400	+1,440
Hours Required to Challenge the Trade	5,400	7,425	+2,025

Program Content: There were some changes to the training content and the sequencing of technical training.

Rationale

In 2019, BC endorsed the Canadian Council of Directors of Apprenticeship (CCDA) recommendations for harmonization and the adoption of a revised Red Seal Occupational Standard (RSOS). Over the course of 2019-2022, BC conducted a review of the BC program with the engagement of our industry and training provider partners. The review aligned the provincial program to the RSOS and the harmonization recommendations.

For more information contact:

Program Standards
email: programstandards@itabc.ca

cc:

All Staff